

Akron Falls Park



2012 - 2014 Capital Improvements:

Project Name	Problem/Issue	Type of Work Completed	Cost to Complete
Valley Bridge Replacement	Poor condition, low bridge rating and weight limit reductions.	Replaced with an entirely brand new bridge structure.	\$653,371.00
Walkway to Falls Repairs	Unsafe and conditions from parking lot to Falls needed to be addressed.	Missing railings installed, walkway surface patched and replaced.	\$9,339.00
Shelter #1 Roof	Condition of roof was terrible (holes) and lots of wood decking rotted underneath.	New roof, and replaced all rotted wood decking.	\$17,674.00
Parkview Comfort Station Roof	Roof was in poor shape and leaking in areas.	Replaced Roof and related carpentry.	\$10,442.00
Parking Lot and Roadway Improvements	Drainage Inlets need replaced and lots/roads that need repairs.	Four (4) DI's replaced, Parkview CS Parking Lot, Road to shelter #3 and east driveway to Cummins Lodge.	\$29,314.00

TOTAL: \$720,140.00